CFAA Practical Exam System Information

To be submitted with Verification Report

Do not answer Questions in the exam form for which the answers are outlined in Red
Fan is powered by FACP
Red LED on relay is sufficient to indicate <i>relay</i> activation.
Duct smoke has tampered cover. Tamper is <i>after</i> the detector.
On Device Record, use "X" to note any deficiencies.
Do not attempt to fix deficiencies.
Repair any wire breaks that you cause.
You may assume that the 3-ring binder of System Documentation is acceptable.
The building is NOT supported with a generator.
The Horn/Strobe is intended to function as a strobe only. Appears as "V" on the Location Sheet.
Battery capacity can be determined by using the load-test meter as opposed to a "loading resistor X time."
You may assume that the wiring/cabling is acceptable. Time does not permit lengthy investigation.
Use this space to show any calculations: